

If your model is not listed, there is no update available.
Please visit your local TOSHIBA Support website or Support Forum for further information.

Firmware update information for
Consumer Products (TV and DVD/BD)



Product Category:	Model year:	Size:	Modelname:	Countrycode:	Latest Version for Download	Network update available ?	Latest Version for Network update	Release Notes (Fixed problems):
TV	2009 A/B	32/37/42	AV623D		2.1.77.2	---	---	
		32/37/42	AV625D		2.1.77.2	---	---	
		32/37/42	AV633D		2.1.77.2	---	---	
		32/37/42	AV635D		2.1.77.2	---	---	
		32/37	AV636D		2.1.77.2	---	---	
		40	LV665P		2.1.77.2	---	---	
		32/40	LV665D		2.1.77.2	---	---	
		32/40	LV675D		2.1.77.2	---	---	
		32/40	LV685D		2.1.77.2	---	---	
		32/37/42	RV623D		2.1.77.2	---	---	
		32/37/42	RV625D		2.1.77.2	---	---	
		32/37/42	RV626D		2.1.77.2	---	---	
		32/37/42	RV633D		2.1.77.2	---	---	
		32/37/42	RV635D		2.1.77.2	---	---	
		32/37/42	RV636D		2.1.77.2	---	---	HDMI Echo symtom fixed --> Link
		32/37/42	RV665D		2.1.77.2	---	---	
		32/37/42	RV675D		2.1.77.2	---	---	
		32/37/42	RV685D		2.1.77.2	---	---	
		46/55	SV675D		2.2.77.2	---	---	
		46/55	SV685D		2.2.77.2	---	---	
		32/37/46	XV625D		2.1.77.2	---	---	
		42	XV626D		2.1.77.2	---	---	
		42	XV632D		2.1.77.2	---	---	
42	XV633D		2.1.77.2	---	---			
32/37/46	XV635D		2.1.77.2	---	---			
42	XV636D		2.1.77.2	---	---			
42/47/55	ZV625D		2.1.77.2	---	---			
42/47/55	ZV635D		2.1.77.2	---	---			
TV	2010 A	32/37/40	RV733	F	10.1.41.9	---	---	
		32/40/46	SL733	F	10.1.41.9	---	---	- Corruption in channel list
		32/40/46	SL736	F	10.1.41.9	---	---	- TV don't come back in last mode after AC power off/on
		32/40/46	VL733	F	10.1.41.9	✓	10.1.41.9	- YouTube XL link don't work
		32/37/40/46	XV733	F	10.1.41.9	---	---	
		32/37/40/46	MV732	G/R	10.1.59.6	---	---	
		32/37/40	RV733	B/G/R	10.1.59.6	---	---	- KDG CI+ CAM not working properly ("CAM removed/inserted message")
		32/40/46	SL733	B/G/R	10.1.59.6	---	---	- Corruption in channel list
		32/40/46	SL736	B/G/R	10.1.59.6	---	---	- TV don't come back in last mode after AC power off/on
		32/40/46	VL733	B/G/R	10.1.59.6	✓	10.1.59.6	- YouTube XL link don't work
		32/40/46	XV733	B/G/R	10.1.59.6	---	---	
		32/40/46	SL753	B	10.2.63.5	---	---	
		32	VL753	B	10.2.63.5	---	---	Fixed an issue with 1080i/p switching with BBC signal in UK
		37/40	RV753	B	10.2.63.5	---	---	
		32/37/40	RV743	G/R	10.3.57.12	✓	10.3.57.12	
		32/37/40	TV743	G/R	10.3.57.12	✓	10.3.57.12	- Loosing transponders in DVB-S channel list
		32/40/46	VL743	G/R	10.3.57.12	✓	10.3.57.12	- Corruption in channel list
		32/37/40/46	XV743	G/R	10.3.57.12	✓	10.3.57.12	- TV don't come back in last mode after AC power off/on
		32/40/46	YL743	G/R	10.3.57.12	✓	10.3.57.12	- YouTube XL link don't work
		32/37/40/46	ZV743	G/R	10.3.57.12	✓	10.3.57.12	
40/46/55	WL753	F	10.4.41.9	✓	10.4.41.9	- Corruption in channel list		
40/46/55	WL753	G/R	10.4.59.5	✓	10.4.59.5	- TV don't come back in last mode after AC power off/on		
40/46/55	WL753	B	10.4.63.5	---	---	- YouTube XL link don't work		
40/46/55	WL743	G/R	10.5.57.12	✓	10.5.57.12	Fixed an issue with 1080i/p switching with BBC signal in UK		
40/46/55	WL743	G/R	10.5.57.12	✓	10.5.57.12	- Loosing transponders in DVB-S channel list		
40/46/55	WL743	G/R	10.5.57.12	✓	10.5.57.12	- Corruption in channel list		

If your model is not listed, there is no update available.
Please visit your local TOSHIBA Support website or Support Forum for further information.

Firmware update information for
Consumer Products (TV and DVD/BD)



Product Category:	Model year:	Size:	Modelname:	Countrycode:	Latest Version for Download	Network update available ?	Latest Version for Network update	Release Notes (Fixed problems):	
TV	2010 B	19/22/26/32/42	SL738	F/G/N/R	V.2.03	---	---	- preventive update for a "CI+" problem - reception problems in Italian DVB-T signal - problems with Italian "play.me" service	
		40/46	VL758	B	17.1.24.12	✓	17.1.24.12		
		40/46	VL748	F/G/R	17.2.24.12	✓	17.2.24.12		
		40/46	XL748	F/G/R	17.2.24.12	✓	17.2.24.12		
		40/46/55	WL768	B/F/G	17.3.24.12	✓	17.3.24.12		
		40	WL768	B	17.3.24.17	---	---	Fixed an issue with 1080i/p switching with BBC signal in UK	
		40/46/55	YL768	G	17.3.24.12	✓	17.3.24.12		
	2011 A	32	AV833	AV833	B/F/N	v1.57	---	---	
			AV833	AV833	G	v1.05	---	---	
			AV834	AV834	B	v1.57	---	---	
			AV834	AV834	G	v1.05	---	---	
			26/32	EL833	B/F/N	v1.57	---	---	
			26/32	EL833	G	v1.05	---	---	
			26/32	EL834	B	v1.57	---	---	
			26/32	EL834	G	v1.05	---	---	
			32/42	HL833	B/F/N	v1.57	---	---	
			32/42	HL833	G	v1.05	---	---	
			32/42	HL834	G	v1.05	---	---	
			32/40	LV833	B/F/N	v1.57	---	---	
			32/40	LV833	G	v1.05	---	---	
			32/37/42	RL833	G/R	17.8.37.1	✓	17.8.37.1	Fixed an issue with 1080i/p switching with BBC signal in UK
			32/37/42	RL853	B	17.9.39.1	✓	17.8.39.1	
		32/37/42	SL833	G	19.1.61.14	✓	19.1.61.14		
		32/37/42	SL833	F/N	19.1.49.236	✓	19.1.41.236	v.61.14 fixed: - YouTube XL playback problems (wrong video scaling) - updated SAT transponder list - fixed a problem with SAT channel list corruption - fixed a problem in Danish STOFA network	
		32/37/42	SL833	R	19.1.61.7	✓	19.1.61.7		
		32/37/42/46	SL863	B/G	19.2.61.14	✓	19.2.61.14		
		32/37/42/46	SL863	F/N	19.2.49.236	✓	19.2.49.236		
		32/37/42/46	SL863	R	19.2.61.7	✓	19.2.61.7		
		32/37/42/46	UL863	B/G	19.3.61.14	✓	19.3.61.14		
		32/37/42/46	UL863	F/N	19.3.49.236	✓	19.3.49.236		
		32/37/42/46	UL863	R	19.3.61.7	✓	19.3.61.7		
		32/37/42/46	UL875	G	19.3.61.14	✓	19.3.61.14		
		42/47	VL863	B/G	19.4.61.14	✓	19.4.61.14		
		42/47	VL863	F/N	19.4.49.236	✓	19.4.49.236		
		42/47	VL863	R	19.4.61.7	✓	19.4.61.7	v.61.15: re-enables MAXDOME playback, that will not work after June2013 with SW versions <=61.14. MAXDOME is only supported by WL863 based models and ZL2.	
		42/46/55	WL863	B/G	19.5.61.14	✓	19.5.61.15		
		42/46/55	WL863	F/N	19.5.49.236	✓	19.5.49.236		
		42/46/55	WL863	R	19.5.61.7	✓	19.5.61.7		
		42/46/55	YL863	B/G	19.5.61.14	✓	19.5.61.14		
		42/46/55	YL863	F/N	19.5.49.236	✓	19.5.49.236		
		42/46/55	YL863	R	19.5.61.7	✓	19.5.61.7		
		42/46/55	YL875	G	19.5.61.14	✓	19.5.61.14		
55	ZL1	F/G/R	19.7.61.14	✓	19.7.61.14				
46/55	ZL2	F/G/R	19.9.62.9	✓	19.9.62.9				

If your model is not listed, there is no update available.
Please visit your local TOSHIBA Support website or Support Forum for further information.

Firmware update information for
Consumer Products (TV and DVD/BD)



Product Category:	Model year:	Size:	Modelname:	Countrycode:	Latest Version for Download	Network update available ?	Latest Version for Network update	Release Notes (Fixed problems):	
TV	2011 B	32/40	RL838	G/F	---	✓	6.4.0Y.1	Release notes for 6.4.xY.1: - Fixed an issue with HbbTV crashing. - Toshiba Places compatibility issues fixed IMPORTANT: Please "RESET" your TV after the network Software update in order that the changes will be applied. Refer to the user manual on how to RESET the set to factory shipout condition. PLEASE NOTICE: individual channel list and personal settings will be deleted after a RESET.	
		32/40	RL858	B	---	✓	6.4.2Y.1		
		32/40	RL838	N	---	✓	6.4.2Y.1		
		32/40/46	TL838	G/F	---	✓	6.4.0Y.1		
		32/40/46	TL868	G/F	---	✓	6.4.0Y.1		
		32/40/47	TL868	B	---	✓	6.4.2Y.1		
		32/40/47	TL868	N	---	✓	6.4.4Y.1		
	2012 A	19	EL933	G		v116	---	---	v116: fixes a problem with wrong Polish TTX characters
		19	EL934	G		v116	---	---	
		19	EL933	RB		v1.25.02	---	---	
		23	EL933	G		v116	---	---	
		23	EL934	G		v116	---	---	
		23	EL933	RK		v1.25.02	---	---	
		26	EL933	B/G/RB		v1.25.02	---	---	1.25.02 fixed: - fixes problems with missing channels / corrupt channellist - fixes a problem with DVB-T demodulation in France
		26	EL934	G		v1.25.02	---	---	
		32	AV933	G/N/RB		v1.25.02	---	---	
		32	AV934	G/RB		v1.25.02	---	---	
		32	EL933	G/N/RB		v1.25.02	---	---	
		32	EL934	G/RB		v1.25.02	---	---	
		32	HL933	B/G/N/RK		v1.25.02	---	---	
		32	LV933	G/N/RB		v1.25.02	---	---	
		40	HL933	B/G/RK		v1.25.02	---	---	
		40	LV933	G/N/RB		v1.25.02	---	---	
		23/32/40	RL933/936	B/G/F/N		6.9.MD.1	✓	6.9.MD.1	
		23/32/40	RL933	R/RB		6.9.MD.1	✓	6.9.MD.1	
		32/40	RL953	B/N		6.9.MD.1	✓	6.9.MD.1	
		32/40	RL953	R/RB		6.9.9E.1	✓	6.9.9E.1	
	32/40	SL970	G		6.9.MD.1	✓	6.9.MD.1		
	32/40/46	TL933/ TL936	G/F		6.9.MD.1	✓	6.9.MD.1		
	32/40/46	TL933	R/RB		6.9.MD.1	✓	6.9.MD.1		
	32/40/46	TL963/ TL966	G/F		6.9.MD.1	✓	6.9.MD.1		
	32/40/46	TL963	R/RB		6.9.9E.1	✓	6.9.9E.1		
	32/40/46	UL975	G		6.9.MD.1	✓	6.9.MD.1		
42/47/55	VL963	B/G/F/N		6.9.MD.1	✓	6.9.MD.1			
42/47/55	VL963	R/RB		6.9.8E.1	✓	6.9.8E.1			
42/47/55	XL975	G		6.9.MD.1	✓	6.9.MD.1			
2012 B	19/22/32	BL502	B		v.0.6.8c	---	---	Fixed instability problems with symptoms like: - set does not power up, only front LED blinking (red/green) - empty or corrupted channel list - missing channels after initial scan	
	32	BL505	B		v.0.6.8c	---	---		
	32	BV502	B		v.0.6.8c	---	---		
	32	BV504	B		v.0.6.8c	---	---		
	32	BV512	B		v.0.6.8c	---	---		
	32	BV702	B		v.0.6.8c	---	---		
	32	BV712	B		v.0.6.8c	---	---		
	19/23/26/32	KL933	R		v.0.6.8c	---	---		
	19/23/26/32	KL934	R		v.0.6.8c	---	---		

If your model is not listed, there is no update available.
Please visit your local TOSHIBA Support website or Support Forum for further information.

Firmware update information for
Consumer Products (TV and DVD/BD)



Product Category:	Model year:	Size:	Modelname:	Countrycode:	Latest Version for Download	Network update available ?	Latest Version for Network update	Release Notes (Fixed problems):
TV	2012B	32/40	RL938	F/G	7.0.28.16.1	✓	7.0.28.16.1	Release notes for 7.0.28.14.1: - extended support of Media Player files - .tp (MPEG2 TS) / .div (DivX 3,4,5,6) / .xvid (Xvid) / .swf (Flash Video) - WIDI 3.5 support - approved for the use in the Ziggo network of NL - fixed a subtitle problem in UK - fixed a problem with subtitle of Canal ready network Additional information: If you YouTube Leanback service doesn't work for you any longer, please update with this version ! IMPORTANT: Please "RESET" your TV after a Software update via network or USB, in order that the changes will be applied. Refer to the user manual on how to RESET the set to factory shipout condition. PLEASE NOTICE: individual channel list and personal settings will be deleted after a RESET.
		32/40	RL939	G	7.0.28.16.1	✓	7.0.28.16.1	
		32/40	RL958	B	7.0.28.16.1	✓	7.0.28.16.1	
		32/40	SL980	G	7.0.28.16.1	✓	7.0.28.16.1	
		40/46	TL938	G	7.0.28.16.1	✓	7.0.28.16.1	
		40/46	TL939	G	7.0.28.16.1	✓	7.0.28.16.1	
		40/46	TL968	B/G	7.0.28.16.1	✓	7.0.28.16.1	
		42/47/55	WL968	B/F/G	7.0.28.16.1	✓	7.0.28.16.1	
		40/46	UL985	G	7.0.28.16.1	✓	7.0.28.16.1	
		42/47/55	YL985	G	7.0.28.16.1	✓	7.0.28.16.1	
	2013	19	BL502	B2	2.19z (low config)	---	---	CORE-SW Update for VESTEL 2013 TV models. Only main application will be updated to the latest available version. This SW update is <u>NOT</u> suitable to recover the set from "no power up / front LED blinking" symptom, as the Bootloader SW & Model related settings are not included. To start the update, insert the USB stick containing the unpacked CORE SW-file, and press: MENU + "1 5 0 5" Do not mix "low config" (Cable/T/Sat models) with "mid config" SW (T2 models only).
		22	L1300A		2.19z (low config)	---	---	
		22	L1333/L1334	B/G	2.19z (low config)	---	---	
		22	L1337D/L1338D	B/G	2.19z (low config)	---	---	
		22	L1353/L1354	R	2.19z (mid config)	---	---	
		24	W1333/W1334	B/G	2.19z (low config)	---	---	
		24	W1337D/W1338D	B/G	2.19z (low config)	---	---	
		24	W1343	G	2.19z (low config)	---	---	
		24	W2300A		2.19z (low config)	---	---	
		32	L1334D	G	2.19z (low config)	---	---	
		32	L1338D	G	2.19z (low config)	---	---	
		32	L1343D	G	2.19z (low config)	---	---	
		32	L1347D	G	2.19z (low config)	---	---	
		32	L1353D	B/N	2.19z (mid config)	---	---	
		32	L1357D	B	2.19z (mid config)	---	---	
		32	W1300A		2.19z (low config)	---	---	
		32	W1333/W1334	B/N	2.19z (low config)	---	---	
		32	W1333D	B/G/N	2.19z (low config)	---	---	
		32	W1334	G	2.19z (low config)	---	---	
		32	W1337D	B/G	2.19z (low config)	---	---	
		32	W1338D	G	2.19z (low config)	---	---	
		32	W1343D	G	2.19z (low config)	---	---	
		32	W1347D	G	2.19z (low config)	---	---	
		40	L1333	B	2.19z (low config)	---	---	
		40	L1333D	B/G	2.19z (low config)	---	---	
		40	L1334D	G	2.19z (low config)	---	---	
		40	L1337D	B	2.19z (low config)	---	---	
		40	L1338D	G	2.19z (low config)	---	---	
		40	L1343D	G	2.19z (low config)	---	---	
		40	L1347D	G	2.19z (low config)	---	---	
40	L1353	B	2.19z (mid config)	---	---			
40	L1353D	B/N	2.19z (mid config)	---	---			
40	L1354	B	2.19z (mid config)	---	---			
40	L1354D	B	2.19z (mid config)	---	---			
40	L1357D	B	2.19z (mid config)	---	---			

If your model is not listed, there is no update available.
Please visit your local TOSHIBA Support website or Support Forum for further information.

Firmware update information for
Consumer Products (TV and DVD/BD)



Product Category:	Model year:	Size:	Modelname:	Countrycode:	Latest Version for Download	Network update available ?	Latest Version for Network update	Release notes (Fixed problems):
TV	2013	32, 39, 50	L2331D	G	1.05.05	---	---	Release notes 1.05.05: - fixes a problem with wrong EPG time in the territory of Spain (incl. Canary Islands).
		32, 39, 50	L2333D	G	1.05.05	---	---	
		32, 39, 50	L2337D	G	1.05.05	---	---	
		32	W2331D	G	1.05.05	---	---	
		32	W2333D	G	1.05.05	---	---	
		32	W2337D	G	1.05.05	---	---	
		32	W4333D	B/F/G	7.1.92.41.01.1	✓	7.1.92.41.01.1	IMPORTANT: if your Firmware version is older than 7.1.56.16.01.1 (otherwise the following has no relevance): if you update the set via network, this will happen via two separate, consecutive updates: No.1 update: will not change the version number. No.2 will update the set to the latest FW version 7.1.56.16.01.1 --> as an alternative, use the USB update, which requires one single step. Version 7.1.92.41.01.1: - Stability improvements and regular bugfixes
		32/39/50	L4333D	G	7.1.92.41.01.1	✓	7.1.92.41.01.1	
		32/39/50	L4353D	B	7.1.92.41.01.1	✓	7.1.92.41.01.1	
		32/39/50	L4353	RB/RK	7.1.92.41.01.1	✓	7.1.92.41.01.1	
		32/39/50	L4353	N	7.1.92.41.01.1	✓	7.1.92.41.01.1	
		32/39/50	L4363D	G	7.1.92.41.01.1	✓	7.1.92.41.01.1	
		32/40	L6353D	B/F	7.1.92.41.01.1	✓	7.1.92.41.01.1	
		32/40	L6353	RK	7.1.92.41.01.1	✓	7.1.92.41.01.1	
		32/40	L6363D	G	7.1.92.41.01.1	✓	7.1.92.41.01.1	
		32/40	L6363D	N	7.1.56.44.01.1	✓	7.1.56.44.01.1	
		40/50	L7333D	G/F	7.1.92.41.01.1	✓	7.1.92.41.01.1	
		40/50	L7353D	B	7.1.92.41.01.1	✓	7.1.92.41.01.1	
		40	L7353/L7356	RK	7.1.92.41.01.1	✓	7.1.92.41.01.1	
		40/50/58	L7363D	B/F/G	7.1.92.41.01.1	✓	7.1.92.41.01.1	
	40/50/58	L7363	RK/RB	7.1.92.41.01.1	✓	7.1.92.41.01.1		
	40/50/58	L7363	N	7.1.56.44.01.1	✓	7.1.56.44.01.1		
	32/40	M6363D	G	7.1.92.41.01.1	✓	7.1.92.41.01.1		
	40/50/58	M8363D	G	7.1.92.41.01.1	✓	7.1.92.41.01.1		
	58/65/84	L9363D	B/G/F/N/S	7.11.80.35.05.1 - 0211	✓	7.11.80.35.05.1 - 0211	SW-version: 7.11.80.35.05.1 - 0211 This version supports input signals with 3840x2160@60Hz via HDMI ("HDMI2.0"). Unpack both files on an empty USB stick, unplug the power cable, insert USB stick to the TV and power on the set. Updates will be detected and run through consecutively.	
	58/65/84	M9363D	G	7.11.80.35.05.1 - 0211	✓	7.11.80.35.05.1 - 0211		
	2014	32	L2433D / 2434D	G	1.05.15	---	---	v.1.05.15: fixes a channel scan problem in UPC cable network.
			L2443D / L2444D	G	1.05.15	---	---	
			L2453D	D/RB	1.05.15	---	---	
			L2454D	G/RB	1.05.15	---	---	
			L2432/2433/2334D	B/G	1.05.15	---	---	
		32	L3433D	G	3.3.6x	---	---	Das Update ist nur relevant für Nutzer im deutschsprachigen Raum (D / A / CH): mit diesem Update wird die "HbbTV" Funktion aktiviert, falls diese auf Ihrem Gerät fehlen sollte. Update Anleitung: - Software auf USB Stick entpacken - USB Stick einstecken - Gerät mit der POWER Taste auf der Fernbedienung einschalten und gleich im Anschluss die Taste "OK" drücken und gedrückt halten, bis die Front-LED beginnt sehr schnell rot/grün zu blinken. Danach OK Taste loslassen und warten bis das Update durchgelaufen ist. Update nicht unterbrechen. - Sobald die Front LED aufgehört zu blinken, startet das Gerät automatisch neu.
			L3443D	G	3.3.6x	---	---	
40, 48			L3443D	G	3.3.6x	---	---	
32		W3433D	G	3.3.6x	---	---	*** Bitte kontaktieren Sie die Hotline aus Ihrem Land für weitergehende Informationen zu diesem Modell: Deutschland: 02131 - 52 40 999 Österreich: 0810 - 14 41 22 Schweiz: 0900 - 57 58 58	
32		W3443D	G	***	---	---		
32/42/47		L6453D	B	8.1.88.07.01.1	✓	8.1.88.07.01.1	IMPORTANT NOTICE: To update the TV via USB: - Insert the USB stick containing the unpacked update file (refer to the instruction on the DL site) - Press the "VOL-" button on the TV side and keep it pressed. - Plug the TV back into AC power while keeping the VOL- button pressed. - Update will start.	
32/42/47		L6463D	G	8.1.88.07.01.1	✓	8.1.88.07.01.1		
42/47/55		L7453D	B	8.1.88.07.01.1	✓	8.1.88.07.01.1		
42/47/55	L7461D/7463D	G/N	8.1.88.07.01.1	✓	8.1.88.07.01.1			
42/47/55	M7463D	G	8.1.88.07.01.1	✓	8.1.88.07.01.1			

If your model is not listed, there is no update available.
Please visit your local TOSHIBA Support website or Support Forum for further information.

Firmware update information for
Consumer Products (TV and DVD/BD)



Product Category:	Model year:	Size:	Modelname:	Countrycode:	Latest Version for Download	Network update available ?	Latest Version for Network update	Release Notes (Fixed problems):
TV with integrated DVD or Blu-ray Player	2010	19/22/26/32	DV733	G/R	v.2.05	---	---	
		19/22	DV734	G	v.2.05	---	---	
	2011	32/42	DB833	B/F/N	v1.57	---	---	
		32/42	DB833	G	v1.05	---	---	
	2012	32	DV502	B	v.0.6.8c	---	---	
		32	DV504	B	v.0.6.8c	---	---	
		19/23/26/32	DL933	B/F/G	v.0.6.8c	---	---	
		19/23/26/32	DL934	B/G	v.0.6.8c	---	---	
		19/22	DL502B	B	v.0.6.8c	---	---	
		22	DL504B	B	v.0.6.8c	---	---	
		22	DL702/704	B/N	v.0.6.8c	---	---	
		22	DL712B	B	v.0.6.8c	---	---	
	2013	19	DL502	B2	2.19z (low config)	---	---	CORE-SW Update for VESTEL 2013 TV-Combo models. Only main application will be updated to the latest available version.
		22	D1333	B/G/N	2.19z (low config)	---	---	This SW update is NOT suitable to recover the set from "no power up / front LED blinking" symptom, as the Bootloader SW & Model related settings are not included.
		22	D1334	B/G	2.19z (low config)	---	---	To start the update, insert the USB stick containing the unpacked CORE SW-file, and press: MENU + "1 5 0 5"
		22	D1337D	B	2.19z (low config)	---	---	Do not mix "low config" (Cable/T/Sat models) with "mid config" SW (T2 models only).
		24	D1333	B/B2	2.19z (low config)	---	---	
		24	D1333	G	2.19z (low config)	---	---	
		24	D1334	B/B2/G	2.19z (low config)	---	---	
		24	D1337D	B	2.19z (low config)	---	---	
32		D1333D	B	2.19z (low config)	---	---		
32		D1334D	B	2.19z (low config)	---	---		
32		D1337D	B	2.19z (low config)	---	---		
32		D1354D	B	2.19z (mid config)	---	---		
32		DL1333	B	2.19z (low config)	---	---		
32		DL1334	B	2.19z (low config)	---	---		
40	D1333	B	2.19z (low config)	---	---			
Blu-ray Player			BDX1100K	B/E	v.50	---	---	
			BDX1200K	B/E	v.16	---	---	
			BDX1250K	B	v.22	✓	v.22	
			BDX1300K	B/E	v.20 / v.24	✓	v.20 / v.24	
			BDX2100K	B/E	v.33	---	---	
			BDX2300K	E	v.0.96	✓	v0.96	
			BDX2400K	B/E	v.33	✓	v0.96	
			BDX3100K	B/E	v.33	---	---	
			BDX3200K	B/E/R	v.25	---	---	
			BDX3300K	B	v.28	✓	v.28	
			BDX3400K	B/E	v0.96	✓	v0.96	
			BDX4300K	B	v.17	✓	v.17	
			BDX4350K	B/E	v.39	---	---	
			BDX4350K	E	v0.96	✓	v0.96	
			BDX5300K	B	v.39	---	---	
			BDX5400K	B/E	v0.96	✓	v0.96	
			BDX6400K	B	v0.68	✓	v0.68	